



Great Slave Helicopters 106 Dickins Street Yellowknife, NT X1A 3T2

Ph. Office: 867-873-2081

Fax:867-873-6087

www.gsheli.com

C-GPGH Detailed View

Registration C-GPGH Date Jun 25, 2021
 Make Bell TTAf 15117.2
 Model 206B Serial No. 4022

Actions

Ann - Annual Recert CAL - CALIBRATION
 INS - INSPECTION ON - ON CONDITION
 OVE - OVERHAUL RET - RETIREMENT

| Cycles values | | | | | | | |
|---------------------|----------|-------------|-------|------------|-------|------------|-------|
| Cycle Name | Value | Cycle Name | Value | Cycle Name | Value | Cycle Name | Value |
| HEATER BLOWER HOURS | 0.0 | HOOK CYCLES | 0.0 | HOOK HOURS | 0.0 | Landings | 0.0 |
| STARTS | 14 125.0 | | | | | | |

Components

| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
|--------------------------------|-----------------------|--------------|---------------|--------------|-------------|-------------------------|---------------|-------------------------|---------------|------|------------------|
| ANNUAL CALENDAR ITEMS / | / | | | | | | | | | | |
| -- BATTERY, NICAD / INS | SAFT/ 023470-000 | 1756 | 09052000E4757 | | 600H 12M | 15114.9H May 8, 2021 | | 15714.9H May 8, 2022 | 2.3H 1.57M | | 597.7H 10.43M |
| -- COMPASS SWING / CAL | BELL HELICOPTER/ | C2300DL4_24B | | | 12M | 15113.8H Apr 8, 2021 | | Apr 8, 2022 | 3.4H 2.57M | | 9.43M |
| -- FIRE EXTINGUISHER / INS | AMEREX/ HALON 1211 | A344 | X-946916 | | 12M | 15113.8H Apr 8, 2021 | | Apr 8, 2022 | 3.4H 2.57M | | 9.43M |
| -- FIRST AID KIT / INS | BRAIDNER/ | AOSHTYPEA | A870-M13 | | 0H 12M | 15113.8H Apr 8, 2021 | | Apr 8, 2022 | 3.4H 2.57M | | 9.43M |
| -- SURVIVAL GEAR / INS | BRAIDNER/ 5x5 | FE5A | A870-0505 | | 12M | 15113.8H Apr 8, 2021 | | Apr 8, 2022 | 3.4H 2.57M | | 9.43M |
| AVIONICS / | / | | | | | | | | | | |
| -- ALTIMETER / CAL | / | 5934-1 | GE756 | | 24M | 15113.8H Apr 7, 2021 | | Apr 7, 2023 | 3.4H 2.6M | | 21.4M |
| -- ELT / Ann | ARTEX/ ME406 | 453-6604 | 15387 | | 24M | 15113.8H Apr 7, 2021 | | Apr 7, 2023 | 3.4H 2.6M | | 21.4M |
| -- ENCODER / CAL | / | A-30 | 126495 | | | 15113.8H | | | 3.4H | | |

Components

| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
|---|--------------------------------|-----------------|-------------------|--------------|---------------|-------------------------------------|---------------|-------------------|-----------------------------|------|------------------|
| | | | | | 24M | Apr 7, 2021 | | Apr 7, 2023 | 2.6M | | 21.4M |
| -- PITOT STATIC SYSTEM / INS | / | | | | 24M | 15113.8H Apr 7, 2021 | | Apr 7, 2023 | 3.4H 2.6M | | 21.4M |
| -- TRANSPONDER / CAL | / | 066-1062-00 | 114733 | | 24M | 15113.8H Apr 7, 2021 | | Apr 7, 2023 | 3.4H 2.6M | | 21.4M |
| CARGO HOOK ASSY / | / | | | | | | | | | | |
| -- CARGO HOOK / OVE Cycle Name : HOOK HOURS | Breeze-Eastern/ | SP-4232-4 | 3065 | | 60M* 1000C | 14039.5H Jun 20, 2017 * 0C | * 33.4C | Apr 21, 2022 * | 1077.7H 48.17M* 33.4C | * | 9.87M* 966.6C |
| CYCLIC TUBE LOWER / ON | / | 206-001-194-001 | USFS6838 | | | 14245.5H Mar 8, 2018 | | | 871.7H 39.57M | | |
| ENGINE / ON | Rolls-Royce/ C20R/2 | 23035212 | CAE-830013 | | | 12107H Feb 27, 2003 | 12107H | | 15117.2H 219.93M | | |
| -- GEARBOX / ON FAP | / | 23035185 | CAG-33013 | | | 13941.3H Apr 29, 2016 | 3090.5H | | 4266.4H 61.87M | | |
| -- _COMPRESSOR / OVE FAP | / | 23050833 | CAC-15105 | | 3500H | 13941.3H Apr 29, 2016 | 0H | 17441.3H | 1175.9H 61.87M | | 2324.1H |
| -- _TURBINE / OVE FAP | / | 23073352 | CAT-36581 | | 3500H | 14039H Jun 20, 2017 | 0H | 17539H | 1078.2H 48.17M | | 2421.8H |
| -- __BLEED VALVE / OVE | / | 230531178 | FF47938 | | 1500H | 14721.3H May 1, 2019 | 0H | 16221.3H | 395.9H 25.8M | | 1104.1H |
| -- __FCU / OVE FA | / | 2549065-7 | BR55330 | | 2500H | 14940.6H May 31, 2020 | 0H | 17440.6H | 176.6H 12.8M | | 2323.4H |
| -- __FUEL NOZZLE / OVE | / | 23077068 | AG45083 | | 2500H | 14421.5H Jun 27, 2018 | 0H | 16921.5H | 695.7H 35.93M | | 1804.3H |
| -- __FUEL PUMP / OVE | / NO EXTENSION ALLOWED | 6899253 | T101597 | | 4500H | 12808.9H May 16, 2012 | 0H | 17308.9H | 2308.3H 109.3M | | 2191.7H |
| -- __PT GOVERNOR & CEB 73-4067 / OVE | / | M250-10847 | 84250119 | | 2000H | 15091H | 1176.7H | 15914.3H | 1202.9H | | 797.1H |

Components

| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
|--|---------------------|-----------------|------------|--------------|--------|---------------------------|---------------|---------------|---------------------|------|---------|
| FA | | | | | | Oct 23, 2020 | | | 8.07M | | |
| FREEWHEEL ASSY & AD / 2016-13R1 / OVE | | 206-040-270-003 | BMB-12240 | | 3000H | 14329H Jun 13, 2018 | | 17329H | 788.2H 36.4M | | 2211.8H |
| HYDRAULIC / | | | | | | | | | | | |
| -- HYDRAULIC PUMP / OVE | Bell/ 206 | 206-076-022-005 | B2517 | | 3600H | 12291.6H Sep 28, 2011 | 0H | 15891.6H | 2825.6H 116.9M | | 774.4H |
| -- M/R SERVO (#1) / OVE / FA | | 206-076-031-017 | RH0058 | | 3600H | 14039.5H Sep 8, 2016 | 0H | 17639.5H | 1077.7H 57.57M | | 2522.3H |
| -- M/R SERVO (#2) / OVE / FA | | 206-076-031-013 | 1068 | | 3600H* | 11458.5H* Jul 15, 2009 | 0H* | 15418.5H* | 3658.7H* 143.33M | * | 301.3H* |
| -- M/R SERVO (#3) / OVE / FA | | 206-076-031-013 | 2722 | | 3600H | 11670.2H Oct 23, 2009 | | 15270.2H | 3447H 140.07M | | 153H |
| -- M/R SERVO (#3) / OVE / FA | | 206-076-031-013 | 5380 | | 3600H | 15116.9H May 16, 2021 | 0H | 18716.9H | 0.3H 1.3M | | 3599.7H |
| -- M/R SERVO SUPPORT / / RET | | 206-001-566-101 | TI374 | | 10000H | 9997.1H Sep 29, 2006 | | 19997.1H | 5120.1H 176.87M | | 4879.9H |
| LOWER COLLECTIVE TUBE / RET | | 206-001-194-001 | USFS6838 | | 4800H | 14245.5H Mar 8, 2018 | 0H | 19045.5H | 871.7H 39.57M | | 3928.3H |
| M/R BLADE (#1) (#1) / RET FAP | Bell/ 206B | 206-010-200-133 | A-7881 | | 5000H | 10567.7H Jul 17, 2007 | | 15567.7H | 4549.5H 167.27M | | 450.5H |
| M/R BLADE (#2) (#2) / RET FAP | Bell/ 206B | 206-010-200-133 | A-7888 | | 5000H | 10567.7H Jul 17, 2007 | | 15567.7H | 4549.5H 167.27M | | 450.5H |
| M/R HUB ASSY (2400 HR / BIG) / OVE FAP | WITH -105 YOKE ONLY | 206-011-100-107 | AAB-05569 | | 2400H | 15113.8H Apr 8, 2021 | | 17513.8H | 3.4H 2.57M | | 2396.6H |
| M/R INPUT DRIVESHAFT / OVE << Not Installed >> | Kamatics/ KaFlex | SKCP2782-1 | | | 6000H* | * | * | May 19, 2021* | * | * | -1.2M* |
| M/R INPUT DRIVESHAFT / OVE | Kamatics/ KaFlex | SKCP2348-5 | 2198 | | 6000H | 13511.4H | 1394.2H | 18117.2H | 3000H | | 3000H |

| Components | | | | | | | | | | | |
|---|---|-----------------------|-------------|--------------|--------------|-----------------------------|---------------|--------------------------|-------------------|------|-------------------|
| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
| | | | | | | Oct 28, 2013 | | | 91.9M | | |
| M/R MAST / OVE FA | | 206-040-002-111 | MFS-7336 | | 3000H | 14367.1H Jul 5, 2018 | 1430.5H | 15936.6H | 2180.6H 35.67M | | 819.4H |
| M/R SWASHPLATE / OVE/ FAP | | 206-010-450-113 | A19-281 | | 4800H | 13762.9H May 16, 2015 | 0.00426H | 18562.9H | 1354.3H 73.3M | | 3445.7H |
| M/R TRANSMISSION & AD 2016-13R1 / OVE FAP | 4 PLANETARY | 206-040-002-027 | BKW-50639 | | 4500H | 14614H Nov 29, 2018 | 1613.5H | 17500.5H | 2116.7H 30.87M | | 2383.3H |
| STARTER GENERATOR / OVE | | 23032-018 | 13661 | | 1000H | 14245.5H Mar 8, 2018 | 0H | 15245.5H | 871.7H 39.57M | | 128.3H |
| T/R CONTROL TUBE / INS | 1200 Hour/24 M onths Componen t Operation/ | | | | 1200H 24M | 15082.7H Oct 14, 2020 | | 16282.7H Oct 14, 2022 | 34.5H 8.37M | | 1165.5H 15.63M |
| T/R DRIVESHAFT (SEGMENTED) / ON | | | | | | | | | | | |
| T/R GEARBOX / OVE FAP | | 206-040-402-105 | AFS-3690 | | 6000H | 14245.5H Mar 6, 2018 | 2995.8H | 17249.7H | 3867.5H 39.63M | | 2132.5H |
| T/R HUB & BLADE ASSY / ON | | 206-011-810- 151VH | TNTRHBA-004 | | 2500H | 13001.2H Nov 29, 2012 | 0H | 15501.2H | 2116H 102.87M | | 384H |
| TAIL BOOM / ON | Bell/ 206B | | | | | | | | | | |

" * " indicates that a Manual Next Due is set./ (p) Indicates that component is affected by penalty factor

| Recurring AD's | | | | | | | | |
|------------------------|--|-------|-------------|--------------------------|-------------------------|-------------------|-----------------|--|
| AD No. | Description | Type | Limit | Perf. | Due | TTSC | Remaining | |
| 2015-02-22 | Failure of 3rd and 4th Stage Turbine Wheel Blades. | Recur | 1750H | 14039.5H Jun 20, 2017 | 15789.5H | 1077.7H 48.17M | 672.3H | |
| 206-21-141 6200 | MAIN ROTOR PITCH LINK ASSEMBLY, INSPECTION AND APPLICATION OF TORQUE SEAL LACQUER. . | Recur | 300H 12M | 15113.8H Apr 8, 2021 | 15413.8H Apr 8, 2022 | 3.4H 2.57M | 296.6H 9.43M | |
| ASB 206-20-139 6510 | Segmented Tail Rotor Drive Shafts with Bonded Adapters, Proof Load Test. | Recur | 300H 12M | 15014.2H Aug 1, 2020 | 15314.2H Aug 1, 2021 | 103H 10.8M | 197H 1.2M | |

| Recurring AD's | | | | | | | |
|---------------------------------|--|-------|-------------|--------------------------|-------------------------|---------------|----------------|
| AD No. | Description | Type | Limit | Perf. | Due | TTSC | Remaining |
| ASB 206-20-139 Rev A 6510 | Segmented Tail Rotor Drive Shafts with Bonded Adapters, Proof Load Test. | Recur | 300H 12M | 15014.2H Aug 1, 2020 | 15314.2H Aug 1, 2021 | 103H 10.8M | 197H 1.2M |
| ASB 206-20-140 6200 | Main Rotor Blades, Grip Plates and Root End Doublers Inspection. | Recur | 100H | 15113.8H Nov 20, 2020 | 15213.8H | 3.4H 7.17M | 96.6H |
| ASB 206-89-48 | FLIGHT CONTROL BOLT INSPECTION. | Recur | 24M | 15113.8H Apr 8, 2021 | Apr 8, 2023 | 3.4H 2.57M | 21.43M |
| ASB 206-97-90 Part III | M/R Pillow Block Torque Check. | Recur | 100H 12M | 15113.8H Apr 8, 2021 | 15213.8H Apr 8, 2022 | 3.4H 2.57M | 96.6H 9.43M |
| CF-2013-28 Para 2 2800 | Decal - Fuel Cell Vent (cancels CF 96-11) TB Ref: 206-95-156 Rev A. | Recur | 300H 12M | 15082.7H Oct 7, 2020 | 15382.7H Oct 7, 2021 | 34.5H 8.6M | 265.5H 3.4M |
| CF-91-35 Part B | Box Beam Inspection. | Recur | 12M | 15082.7H Oct 7, 2020 | Oct 7, 2021 | 34.5H 8.6M | 3.4M |
| CF-96-11 | Fuel Cell Vent Tube Decal (CF-2013-28 cancels this AD). | Recur | 300H 12M | 15082.7H Oct 7, 2020 | 15382.7H Oct 7, 2021 | 34.5H 8.6M | 265.5H 3.4M |

" * " indicates that a Manual Next Due is set.

| Inspections | | | | | |
|---|-------------|--------------------------|-------------------------|---------------|---------------|
| Inspection | Limit | Perf. | Due | TTSC | Remaining |
| 100 HOUR AIRFRAME INSPECTION - Reference MM-5-20 & 5-16 thru 5-19 | 100H 12M | 15082.7H Oct 7, 2020 | 15182.7H Oct 7, 2021 | 34.5H 8.6M | 65.5H 3.4M |
| 100 hrs W&B DOCUMENTATION CHECK | 100H | 15116.9H May 16, 2021 | 15216.9H | 0.3H 1.3M | 99.7H |
| 12 MONTH AIRFRAME INSPECTION - Reference MM-5-33 | 12M | 15113.8H Apr 8, 2021 | Apr 8, 2022 | 3.4H 2.57M | 9.43M |
| 12 MONTH OF COMPONENT OPERATION - Reference MM-5-34 | 12M | 15113.8H Apr 8, 2021 | Apr 8, 2022 | 3.4H 2.57M | 9.43M |
| 150 HOUR ENGINE INSPECTION - Reference M250-C20, 72-00-00 Table 603 | 100H | 15082.7H Oct 7, 2020 | 15182.7H | 34.5H 8.6M | 65.5H |
| 24 MONTH AIRFRAME INSPECTION - Reference MM-5-35 | 24M | 15113.8H Apr 8, 2021 | Apr 8, 2023 | 3.4H 2.57M | 21.43M |

| Inspections | | | | | |
|--|-------------|--------------------------|--------------------------|----------------|-----------------|
| Inspection | Limit | Perf. | Due | TTSC | Remaining |
| 25 HOUR GREASING | 25H 1.5M | 15113.8H Apr 8, 2021 | 15138.8H May 23, 2021 | 3.4H 2.57M | 21.6H -1.07M |
| 300 HOUR AIRFRAME INSPECTION - Reference MM-5-29 | 300H | 15082.7H Oct 7, 2020 | 15382.7H | 34.5H 8.6M | 265.5H |
| 300 HOUR ENGINE INSPECTION - Reference M25-C20, 72-00-00 Table 603 | 300H | 15082.7H Oct 7, 2020 | 15382.7H | 34.5H 8.6M | 265.5H |
| Aircraft Spares - Consumables Check | 6M* | * | Jun 12, 2020 * | * | -12.43M* |
| CORROSION INSPECTION | 100H 3M | 15117.2H May 16, 2021 | 15217.2H Aug 16, 2021 | 0H 1.3M | 100H 1.7M |
| ENGINE OIL REPLACEMENT | 600H | 15113.8H Apr 14, 2021 | 15713.8H | 3.4H 2.37M | 596.6H |
| MGB OIL FILTER & OIL REPLACEMENT | 200H | 15082.7H Oct 14, 2020 | 15282.7H | 34.5H 8.37M | 165.5H |
| POWER CHECK | 100H | 15082.9H Oct 14, 2020 | 15182.9H | 34.3H 8.37M | 65.7H |

" * " indicates that a Manual Next Due is set.

| ELT - Assembly - PN: 453-6604 SN: 15387 | | | | | | | | | | | |
|---|-----------------|----------|------------|--------------|-------|-----------------------------|---------------|----------------|---------------|------|---------|
| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
| ELT / Ann | ARTEX/ ME406 | 453-6604 | 15387 | | 24M | 15113.8H Apr 7, 2021 | | Apr 7, 2023 | 3.4H 2.6M | | 21.4M |
| -- ELT BATTERY / REP | ARTEX/ | 452-6499 | | | 60M* | 15113.8H Apr 7, 2021 * * | | Apr 7, 2028 * | 3.4H 2.6M* | * | 81.4M* |
| -- OPERATIONAL TEST / Tes | / | | | | 12M* | 15113.8H Apr 7, 2021 * * | | May 20, 2022 * | 3.4H 2.6M* | * | 10.83M* |

| FIRE EXTINGUISHER - Assembly - PN: A344 SN: X-946916 |
|--|
|--|

| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
|---------------------------|-----------------------|-----------|------------|--------------|-------|-------------------------|---------------|--------------|---------------|------|-------|
| FIRE EXTINGUISHER / INS | AMEREX/ HALON 1211 | A344 | X-946916 | | 12M | 15113.8H Apr 8, 2021 | | Apr 8, 2022 | 3.4H 2.57M | | 9.43M |
| -- HYDROSTATIC TEST / RET | / | HALON1211 | X-102167 | | 144M | Jan 10, 2010 | | Jan 10, 2022 | 137.5M | | 6.5M |

FREEWHEEL ASSY & AD 2016-13R1 - Assembly - PN: 206-040-270-003 SN: BMB-12240

| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
|--|------------|-----------------|------------|--------------|-------|------------------------|---------------|----------|------------------|------|---------|
| FREEWHEEL ASSY & AD 2016-13R1 / OVE | / | 206-040-270-003 | BMB-12240 | | 3000H | 14329H Jun 13, 2018 | | 17329H | 788.2H 36.4M | | 2211.8H |
| -- 1500 HOUR INSPECTION & AD 2016-13R1 / INS | / | | | | 1500H | 14329H Jun 13, 2018 | | 15829H | 788.2H 36.4M | | 711.8H |
| -- CLUTCH / RET | / | CL42250-1 | FD18155 | | 3000H | 14329H Jun 13, 2018 | 1487.2H | 15841.8H | 2275.4H 36.4M | | 724.6H |

M/R HUB ASSY (2400 HR BIG) - Assembly - PN: 206-011-100-107 SN: AAB-05569

| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
|--------------------------------------|---------------------|-----------------|------------|--------------|-------|-------------------------|---------------|----------|------------------|------|---------|
| M/R HUB ASSY (2400 HR BIG) / OVE FAP | WITH -105 YOKE ONLY | 206-011-100-107 | AAB-05569 | | 2400H | 15113.8H Apr 8, 2021 | | 17513.8H | 3.4H 2.57M | | 2396.6H |
| -- 1200 HOUR INSPECTION / INS | / | | | | 1200H | 15113.8H Apr 8, 2021 | | 16313.8H | 3.4H 2.57M | | 1196.6H |
| -- GRIP (#1) / RET | / | 206-011-132-113 | HB6900 | | 4800H | 15113.8H Apr 8, 2021 | 1353.7H | 18560.1H | 1357.1H 2.57M | | 3442.9H |
| -- GRIP (#2) / RET | / | 206-011-132-113 | HB7290 | | 4800H | 15113.8H Apr 8, 2021 | | 19913.8H | 3.4H 2.57M | | 4796.6H |
| -- LATCH BOLT (#1) / RET | / | 206-011-260-103 | SU8096 | | 2500H | 15113.8H Apr 8, 2021 | 1349.7H | 16264.1H | 1353.1H 2.57M | | 1146.9H |
| -- LATCH BOLT (#2) / RET | / | 206-011-260-103 | SU8101 | | 2500H | 15113.8H Apr 8, 2021 | 1349.7H | 16264.1H | 1353.1H 2.57M | | 1146.9H |
| -- M/R YOKE / ON | / | 206-011-149-105 | 3615 | | | 15113.8H | 1349.7H | | 1353.1H | | |

| M/R HUB ASSY (2400 HR BIG) - Assembly - PN: 206-011-100-107 SN: AAB-05569 | | | | | | | | | | | |
|--|------------|----------------------|------------|--------------|---------------|-----------------------------------|---------------|-------------------------------|------------------------|------|-------------------|
| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
| | | | | | | Apr 8, 2021 | | | 2.57M | | |
| -- STRAP FITTING / RET | / | 206-011-150-105 | HB12985 | | 2400H | 15113.8H Apr 8, 2021 | 1349.7H | 16164.1H | 1353.1H 2.57M | | 1046.9H |
| -- STRAP FITTING / RET | / | 206-011-150-105 | HB13103 | | 2400H | 15113.8H Apr 8, 2021 | | 17513.8H | 3.4H 2.57M | | 2396.6H |
| -- STRAP PIN / RET | / | 2AA-011-125-105 | DI37923 | | 2500H | 15113.8H Apr 8, 2021 | 1349.7H | 16264.1H | 1353.1H 2.57M | | 1146.9H |
| -- STRAP PIN / RET | / | 2AA-011-125-105 | DI37937 | | 2500H | 15113.8H Apr 8, 2021 | 1349.7H | 16264.1H | 1353.1H 2.57M | | 1146.9H |
| -- TRUNNION / RET Cycle Name : STARTS | / | 206-01-113-103 | HB3062 | | 4800H | 15113.8H Apr 8, 2021 14118C | 1349.7H | 18564.1H | 1353.1H 2.57M 7C | | 3446.9H |
| -- TT STRAP -310 / RET | / | 206-310-004-101/-103 | LKFS0127 | | 1200H 48M* | 15113.8H Apr 8, 2021 * | 347H * | 15966.8H May 18, 2022 * | 350.4H 2.57M* | * | 849.6H 10.77M* |
| -- TT STRAP -310 / RET | / | 206-310-004-101/-103 | LKFS0142 | | 1200H 48M | 15113.8H Apr 8, 2021 | 347H | 15966.8H Apr 8, 2025 | 350.4H 2.57M | | 849.6H 45.43M |

| M/R INPUT DRIVESHAFT - Assembly - PN: SKCP2782-1 | | | | | | | | | | | |
|---|---------------------|------------|------------|--------------|------------|-------|---------------|--------------|------|------|--------|
| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
| M/R INPUT DRIVESHAFT / OVE << Not Installed >> | Kamatics/ KaFlex | SKCP2782-1 | | | 6000H * | * | * | May 19, 2021 | ** | * | -1.2M* |
| -- 1500 HOUR INSPECTION / Ins << Not Installed >> | / | | | | 1500H * | * | * | May 19, 2021 | ** | * | -1.2M* |

| M/R INPUT DRIVESHAFT - Assembly - PN: SKCP2348-5 SN: 2198 | | | | | | | | | | | |
|--|---------------------|------------|------------|--------------|-------|--------------------------|---------------|----------|----------------|------|--------|
| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
| M/R INPUT DRIVESHAFT / OVE | Kamatics/ KaFlex | SKCP2348-5 | 2198 | | 6000H | 13511.4H Oct 28, 2013 | 1394.2H | 18117.2H | 3000H 91.9M | | 3000H |
| -- 1500 HOUR INSPECTION / Ins | / | | | | 1500H | 14614.1H | | 16114.1H | 503.1H | | 996.9H |

M/R INPUT DRIVESHAFT - Assembly - PN: SKCP2348-5 SN: 2198

| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
|------------------|------------|----------|------------|--------------|-------|-------------|---------------|-----|-------|------|------|
| | | | | | | Nov 7, 2018 | | | 31.6M | | |

M/R MAST - Assembly - PN: 206-040-002-111 SN: MFS-7336

| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
|-------------------------------|------------|-----------------|------------|--------------|-------|-------------------------|---------------|----------|-------------------|------|--------|
| M/R MAST / OVE FA | / | 206-040-002-111 | MFS-7336 | | 3000H | 14367.1H Jul 5, 2018 | 1430.5H | 15936.6H | 2180.6H 35.67M | | 819.4H |
| -- 1500 HOUR INSPECTION / INS | / | | | | 1500H | 14367.1H Jul 5, 2018 | | 15867.1H | 750.1H 35.67M | | 749.9H |
| -- BEARING / ON | / | 206-040-036-103 | MB178 | | | 14367.1H Jul 5, 2018 | | | 750.1H 35.67M | | |
| -- MAST / ON FAP | / | 206-010-322-121 | NFS-7336 | | | 14369.1H Jul 5, 2018 | 9712.9H | | 10461H 35.67M | | |

M/R SWASHPLATE - Assembly - PN: 206-010-450-113 SN: A19-281

| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
|-----------------------------------|------------|----------------------|------------|--------------|--------|--------------------------|---------------|----------|------------------|------|----------|
| M/R SWASHPLATE / OVE FAP | / | 206-010-450-113 | A19-281 | | 4800H | 13762.9H May 16, 2015 | 0.00426H | 18562.9H | 1354.3H 73.3M | | 3445.7H |
| -- COLLECTIVE IDLER LINK / RET | Bell/ | 206-010-407-001 | REFS5924 | | 4800H | 14839.1H Jul 31, 2019 | 0H | 19639.1H | 278.1H 22.8M | | 4521.9H |
| -- COLLECTIVE LEVER / RET | Bell/ | 206-010-467-001/-105 | REFS4155 | | 4800H | 13762.9H May 16, 2015 | 2857.9H | 15705H | 4212.2H 73.3M | | 587.8H |
| -- SLEEVE / RET FA | Bell/ | 206-010-454-109/-113 | RE9359 | | 14400H | 13762.9H May 16, 2015 | 2248.2H | 25914.7H | 3602.5H 73.3M | | 10797.5H |
| -- SUPPORT / ON FA | Bell/ | 206-010-452-113 | A-2534 | | | 13762.9H May 16, 2015 | 4446.6H | | 5800.9H 73.3M | | |

M/R TRANSMISSION & AD 2016-13R1 - Assembly - PN: 206-040-002-027 SN: BKW-50639

| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
|------------------|------------|----------|------------|--------------|-------|-------|---------------|-----|------|------|------|
|------------------|------------|----------|------------|--------------|-------|-------|---------------|-----|------|------|------|

| M/R TRANSMISSION & AD 2016-13R1 - Assembly - PN: 206-040-002-027 SN: BKW-50639 | | | | | | | | | | | |
|---|-------------------|-----------------|-------------------|---------------------|--------------|--------------------------|----------------------|------------|-------------------|-------------|-------------|
| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
| M/R TRANSMISSION & AD 2016-13R1 / OVE FAP | 4 PLANETARY | 206-040-002-027 | BKW-50639 | | 4500H | 14614H Nov 29, 2018 | 1613.5H | 17500.5H | 2116.7H 30.87M | | 2383.3H |
| -- 1500 HOUR INSPECTION & AD 2016-13R1 / INS | | | | | 1500H | 14614.7H Nov 30, 2018 | | 16114.7H | 502.5H 30.83M | | 997.5H |

| SURVIVAL GEAR - Assembly - PN: FE5A SN: A870-0505 | | | | | | | | | | | |
|--|--------------------|-----------------|-------------------|---------------------|--------------|---------------------------|----------------------|----------------|------------------|-------------|-------------|
| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
| SURVIVAL GEAR / INS | BRAIDNER/ 5x5 | FE5A | A870-0505 | | 12M | 15113.8H Apr 8, 2021 | | Apr 8, 2022 | 3.4H 2.57M | | 9.43M |
| -- FLARES OR STROBE LIGHT / RET << Not Installed >> | 3 FLARES/1 STROBE/ | | | | | | | | | | |
| -- HAND WARMERS / RET << Not Installed >> | x7/ | | | | | | | | | | |
| -- INSECT REPELLENT / RET << Not Installed >> | x7/ | | | | | | | | | | |
| -- LIGHT STICKS / RET << Not Installed >> | x4/ | | | | | | | | | | |
| -- PORTABLE COMPASS / RET << Not Installed >> | x1/ | | | | | | | | | | |
| -- RATIONS / RET | x10/ | | | | * | 14329H Jun 13, 2018 ** | | Jun 13, 2023 * | 788.2H 36.4M* | * | 23.6M* |
| -- SALT PACKS / RET << Not Installed >> | x7/ | | | | | | | | | | |
| -- SOUP PACKS / RET << Not Installed >> | x7/ | | | | | | | | | | |
| -- TEA BAGS / RET << Not Installed >> | x20/ | | | | | | | | | | |
| -- WATER PURIFICATION TABLETS / RET << Not Installed >> | x1/ | | | | | | | | | | |

| T/R GEARBOX - Assembly - PN: 206-040-402-105 SN: AFS-3690 | | | | | | | | | | | |
|--|-------------------|-----------------|-------------------|---------------------|--------------|-------------------------|----------------------|------------|-------------------|-------------|-------------|
| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
| T/R GEARBOX / OVE FAP | / | 206-040-402-105 | AFS-3690 | | 6000H | 14245.5H Mar 6, 2018 | 2995.8H | 17249.7H | 3867.5H 39.63M | | 2132.5H |

| T/R GEARBOX - Assembly - PN: 206-040-402-105 SN: AFS-3690 | | | | | | | | | | | |
|--|------------|-----------------|------------|--------------|-------|-------------------------|---------------|----------|------------------|------|---------|
| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
| -- 3000HR INSPECTION / INS | / | | | | 3000H | 14245.5H Mar 6, 2018 | | 17245.5H | 871.7H 39.63M | | 2128.3H |
| -- DUPLEX BEARING REPLACEMENT / RET | / | 206-040-410-101 | MB6064 | | 3000H | 14245.5H Mar 6, 2018 | | 17245.5H | 871.7H 39.63M | | 2128.3H |

| T/R HUB & BLADE ASSY - Assembly - PN: 206-011-810-151VH SN: TNTRHBA-004 | | | | | | | | | | | |
|--|------------|-------------------|-------------|--------------|-------|--------------------------|---------------|----------|--------------------|------|--------|
| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
| T/R HUB & BLADE ASSY / ON | / | 206-011-810-151VH | TNTRHBA-004 | | 2500H | 13001.2H Nov 29, 2012 | 0H | 15501.2H | 2116H 102.87M | | 384H |
| -- T/R BLADE (#1) / RET FAP | VHA/ | 2062200-301 | A752 | | 5000H | 13001.2H Nov 29, 2012 | | 18001.2H | 2116H 102.87M | | 2884H |
| -- T/R BLADE (#2) / RET FAP | VHA/ | 2062200-301 | A764 | | 5000H | 13001.2H Nov 29, 2012 | 0H | 18001.2H | 2116H 102.87M | | 2884H |
| -- T/R HUB ASSY / OVE | / | 206-011-810-153 | TNTRHBA-004 | | 2500H | 13001.2H Nov 29, 2012 | 0H | 15501.2H | 2116H 102.87M | | 384H |
| -- T/R YOKE / RET | / | 206-011-819-109 | HBFS-3546 | | 5000H | 13001.2H Nov 29, 2012 | 2437.9H | 15563.3H | 4553.9H 102.87M | | 446.1H |

| COMPRESSOR - Assembly - PN: 23050833 SN: CAC-15105 | | | | | | | | | | | |
|---|------------|----------|------------|--------------|--------|--------------------------|---------------|----------|-------------------|------|---------|
| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
| COMPRESSOR / OVE FAP | / | 23050833 | CAC-15105 | | 3500H | 13941.3H Apr 29, 2016 | 0H | 17441.3H | 1175.9H 61.87M | | 2324.1H |
| -- 1750 HOUR INSPECTION / INS | / | | | | 1750H | 13941.3H Apr 29, 2016 | 0H | 15691.3H | 1175.9H 61.87M | | 574.1H |
| -- 1ST STAGE WHEEL / RET | / | 23032621 | E257892 | | 7500H | 13941.3H Apr 29, 2016 | 3521.9H | 17919.4H | 4697.8H 61.87M | | 2802.2H |
| Cycle Name : STARTS | | | | | 15000C | 4071C | 4071C | 15000C | 14125C | | 875C |
| -- 2ND STAGE WHEEL / RET | / | 23035252 | E258607 | | 7500H | 13941.3H Apr 29, 2016 | 3521.9H | 17919.4H | 4697.8H 61.87M | | 2802.2H |
| Cycle Name : STARTS | | | | | 15000C | 4017C | 4071C | 14946C | 14179C | | 821C |
| -- 3RD STAGE WHEEL / RET | / | 23079006 | QC18550 | | 7500H | 13941.3H Apr 29, 2016 | 3521.9H | 17919.4H | 4697.8H 61.87M | | 2802.2H |

COMPRESSOR - Assembly - PN: 23050833 SN: CAC-15105

| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
|--------------------------|------------|---------------------------|------------|--------------|--------|--------------------------|---------------|----------|-------------------|------|---------|
| Cycle Name : STARTS | | | | | 15000C | 4071C | 4071C | 15000C | 14125C | | 875C |
| -- 4TH STAGE WHEEL / RET | / | 23035254 | E82067 | | 7500H | 13941.3H Apr 26, 2018 | 3521.9H | 17919.4H | 4697.8H 37.97M | | 2802.2H |
| Cycle Name : STARTS | | | | | 15000C | 4071C | 4071C | 15000C | 14125C | | 875C |
| -- IMPELLER / RET | / | Rolls-Royce/C20R/23039065 | JY104476 | | 7500H | 13941.3H Apr 29, 2016 | 3521.9H | 17919.4H | 4697.8H 61.87M | | 2802.2H |
| Cycle Name : STARTS | | | | | 15000C | 4071C | 4071C | 15000C | 14125C | | 875C |

_TURBINE - Assembly - PN: 23073352 SN: CAT-36581

| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
|-------------------------------|------------|------------|------------|--------------|-------|--------------------------|---------------|----------|-------------------|------|---------|
| _TURBINE / OVE FAP | / | 23073352 | CAT-36581 | | 3500H | 14039H Jun 20, 2017 | 0H | 17539H | 1078.2H 48.17M | | 2421.8H |
| -- 1750 HOUR INSPECTION / INS | / | | | | 1750H | 14039.5H Jun 20, 2017 | | 15789.5H | 1077.7H 48.17M | | 672.3H |
| -- 1ST STAGE WHEEL / RET | / | M250-10223 | X636657 | | 1775H | 14039.5H Jun 20, 2017 | | 15814.5H | 1077.7H 48.17M | | 697.3H |
| Cycle Name : STARTS | | | | | 3000C | 12570C | | 15570C | 1555C | | 1445C |
| -- 2ND STAGE WHEEL / RET | / | 23073854 | X643803 | | 1775H | 14039.5H Jun 20, 2016 | | 15814.5H | 1077.7H 60.17M | | 697.3H |
| Cycle Name : STARTS | | | | | 3000C | 12570C | | 15570C | 1555C | | 1445C |
| -- 3RD STAGE WHEEL / RET | / | 23065818 | X641222 | | 4550H | 14039.5H Jun 20, 2016 | | 18589.5H | 1077.7H 60.17M | | 3472.3H |
| Cycle Name : STARTS | | | | | 6000C | 12570C | | 18570C | 1555C | | 4445C |
| -- 4TH STAGE WHEEL / RET | / | 23055944 | X571291 | | 4550H | 14039.5H Jun 20, 2017 | 3231.3H | 15358.2H | 4309H 48.17M | | 241H |
| Cycle Name : STARTS | | | | | 6000C | 12570C | 3720C | 14850C | 5275C | | 725C |
| -- G.P. TIEBOLT / RET | / | 23068265 | NM83045 | | | Jun 20, 2017 | | | 48.17M | | |
| Cycle Name : STARTS | | | | | 9000C | 12570C | 3936C | 17634C | 5491C | | 3509C |

_FCU - Assembly - PN: 2549065-7 SN: BR55330

| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
|---------------------|------------|-----------|------------|--------------|-------|--------------------------|---------------|----------|-----------------|------|---------|
| _FCU / OVE FA | / | 2549065-7 | BR55330 | | 2500H | 14940.6H May 31, 2020 | 0H | 17440.6H | 176.6H 12.8M | | 2323.4H |
| -- FCU FILTER / RET | / | 2539509 | | | 1500H | 14940.6H May 31, 2020 | | 16440.6H | 176.6H 12.8M | | 1323.4H |

PT GOVERNOR & CEB 73-4067 - Assembly - PN: M250-10847 SN: 84250119

| Component/Action | Make/Model | Part No. | Serial No. | Tracking No. | Limit | Perf. | Time at Inst. | Due | TTSC | TTSN | Rem. |
|--|------------|------------|------------|--------------|-------|------------------------|---------------|----------|------------------|------|--------|
| PT GOVERNOR & CEB 73-4067 / OVE FA | / | M250-10847 | 84250119 | | 2000H | 15091H Oct 23, 2020 | 1176.7H | 15914.3H | 1202.9H 8.07M | | 797.1H |